

1188 East Main Street, Grass Valley, CA 95945-5710 (530) 273-7284, FAX (530) 273-9507 E.L.A.P. Certification No. 1936

Donner Summit P.U.D. P.O. Box 610 Soda Springs CA 95728 Job Number: 6090095 Date Reported: 01/28/09 Date / Time Received: 01/15/09 16:00 System Number: 2910016

Sample Number: 6090095 - 1

Sample Site: R-1 Date / Time Collected: 01/15/09 11:00

Parameter Nitrate as N	Analysis Result ND	Reporting Units mg/L	Analytical Method EPA 300.0	Date of Analysis 01/16/2009	Reporting Limit 0.1
Phosphate as P	ND	mg/L	EPA 365.2	01/16/2009	0.01
Total Phosphorus as P, Persulfate-Acid Dgt	ND	mg/L	SM(18) 4500 P	01/26/2009	0.01

Sample Number: 6090095 - 2

Sample Site: R-2 Date / Time Collected: 01/15/09 10:45

Sample Collected By: Jim King

Sample Collected By: Jim King

Parameter	Analysis Result	Reporting Units	Analytical Method	Date of Analysis	Reporting Limit
Nitrate as N	ND	mg/L	EPA 300.0	01/16/2009	0.1
Phosphate as P	ND	mg/L	EPA 365.2	01/16/2009	0.01
Total Phosphorus as P, Persulfate-Acid Dgt	0.02	mg/L	SM(18) 4500 P	01/26/2009	0.01

Sample Number: 6090095 - 3

Sample Site: Towel Mountain Date / Time Collected: 01/15/09 11:20

Sample Collected By: Jim King

Parameter	Analysis Result	Reporting Units	Analytical Method	Date of Analysis	Reporting Limit
Nitrate as N	ND	mg/L	EPA 300.0	01/16/2009	0.1
Phosphate as P	ND	mg/L	EPA 365.2	01/16/2009	0.01
Total Phosphorus as P, Persulfate-Acid Dgt	0.02	mg/L	SM(18) 4500 P	01/26/2009	0.01

Note: "ND" means "none detected" (ie, none was found in the sample at or above the reporting limit).

cc: Brentwood Inc.

cc: Brentwood Inc.



Cranmer Analytical Laboratory		OF CUS	TODY	$\frac{Preservation (P)}{A = Cold}$ $B = HNO_3$ $C = HC1$ $D = H_2SO_4$ $E = NaOH$	$\frac{Container}{I = Intact}$ $B = Broken$ $L = Leaked$ * = Bubbles in VOA <u>Appearance</u>	
1188 E. Main Street – Grass Valley, CA 95945 530-273-7284 FAX: 530-273-9507	loĈ	90094/1009	10095		C = Clear $T = Turbid$ $S = Sediment$	
Client: Donner Summit PUD	Phone: 530 426-9144	ANA	LYSIS REQUIRED	CONT	AINERS/PRESERVATION REC	EIPT
Mailing Address: PUBOX 610	FAX:					
Solo Springs CH 95728	PO #:			P L		C A P
Project Name: Donner Summit PUP	Project #:	1 200		A		N P
Project Manager: Jim King 1				ST		T E A A
Sampled By (sign): in the fland Schatt	(Print): Jim King	2 20		I		A A I R
Special Instructions:		442		C		N A
		CH Zag				E N R C
Lab No. Sample Identity	Date Time Matrix			# P	P # P # P #	E
1994-1 Influent Composite	1-15-09 3900			10	13	_
094-2 Effluent Composite	45-09 0730	XX) A		
FOGS-1 D-1	1-15-09 11:00			1 4		
Profess D-2	1-15-09 11:45					-
0595-3 Towel Mountain	1-15-09 1045			I A		-
Malt-2 Eff Gach	1509 11:20					-
and a prop	1207 11:20					
					┽┼┼┼┼┠┼	
					┿┽┾┼┼╂┼	
					┿┼┼┼┼┠┾	
					┿┼┼┼┽╏┼	+
RELINQUISHED BY (SIGN) PRINT N	AME/COMPANY	DATE/TIME	RECEIVED B	Y (SIGN)	PRINT NAME/COMPAN	Y
1 Pol Shit (ANI Sel	HOTT DSPUD	1/15/29	alame T		Lagne Giles/cranm	
	1 - 1 - 0	44 101		n n	Unit Unes/ Chain	1.(1
Rec'd at lab by:	Date/Time:		Comments:	I		
SHIPPED VIA EFED X EPUPS	CAO/N DOTH	ER:	All hazardous	waste samples will be return	ned to client or billed for disposal.	